Date: **21 July 2021**
Product: **Hughes 9211 and 9202M**
Release: **6.0.0.9**
Importance: **Optional**

Software version 6.0.0.9 for the Hughes 9211 and 9202M terminals is an optional upgrade with some new features. However, if you have not yet upgraded to at least 6.0.0.4 then upgrade now because 6.0.0.4 and above include a fix that corrects the power on/off sequencing to prevent power transients that can cause component failures in some scenarios.

The new upgrader is **9211_Upgrader_6_0_0_9_PC.exe** and is available through both the Inmarsat support page: http://www.inmarsat.com/support/bgan-firmware/ and the Hughes BGAN support page: http://www.bgan.hughes.com

Release Notes for 6.0.0.9 (Since 6.0.0.6)

Enhancements and Bug Fixes
- Set the remote SMS password to blank by default.
- Correctly store the calling number in circuit.csv for MT calls.
- In NAPT mode the standard and streaming usage counts were displayed as 0 until a PDP context was established.
- Correctly display the WLAN card status if the UT IP subnet is changed.
- Fixed an issue where the username and password for a custom (non-default) APN were not saved when defining an ACA context on the ACA Web page.
- Removed the Features Web page. Feature codes are no longer required.
- Fixed Web UI issue where for some operations (such as reboot) the UI accepted an incorrect Admin password and performed the requested operation.
- Fixed Web UI issue with dynamic entry of APN password.
- The release includes BPS 3.1.1.
- The SVN for this release is 10.

Should you have any questions regarding this notice please do not hesitate to contact Hughes at mobilesatellitesupport@hughes.com